

# IMSAI ECO 24-0005

---

*Engineering Change Order for: SIO 2 Rev-3*

## Summary

Component substitutions due to obsolescence.

## Details

The following components may have been discontinued and may be substituted according to the following table:

Parastream / IMSAI Part #	Component	Designators	Parastream / IMSAI Part #	Substitution
<b>36-1000800 / 36-0740801</b>	7408 4×2-In AND PDIP	C4, C6	36-10500800 / 36-0740802	74LS08 4×2-In AND PDIP
<b>36-10009300 / 36-0749301</b>	7493 4-Bit Binary Counter PDIP	A11, A12, B12, C12	36-10509300 / 36-0749302	74LS93 4-Bit Binary Ctr PDIP

## Notes

These substitutions are not mandatory if all the components in the table are available. All or none of the component substitutions must be made. No individual substitutions are allowed.

These component substitutions reduce the overall power consumption.

# Document Revision History

Revision	Date	Initial	Description
0	2024-08-29	REW	Original.