

IMSAI ECO 24-0008

Engineering Change Order for: CP-A Rev-4

Summary

Component substitution to improve customer assembly experience.

Details

The original unthreaded #6 × ¼ × ¼" spacers tended to fall off the button head screws when the customer was attempting to mount the front panel assembly to the cabinet front frame. These unthreaded spacers have been replaced with #8-32 × ¼ × ¼" threaded spacers (standoffs), which tend to stick to the button head screws while the front panel assembly is being moved into position for mounting.

The substitute spacers are the same outer diameter as the original and should appear identical once completely mounted.

Parastream / IMSAI Part #	Component	Parastream / IMSAI Part #	Substitution
21-30205004 / 21-3600001	Spacer #6×¼"×¼" Nylon	21-36145004 / N/A	Spacer #8-32×¼"×¼" Nylon

Document Revision History

Revision	Date	Initial	Description
0	2024-08-29	REW	Original.