IMSAI ECO 24-0002

Engineering Change Order for: MPU-A Rev-4

Summary

Component substitutions due to obsolescence.

Details

The following components may have been discontinued and may be substituted according to the following table:

| Parastream / IMSAI Part # | Component | Designators | Parastream / IMSAI Part # | Substitution |
|---------------------------|---------------|-------------|---------------------------|----------------|
| 36-10007400 / | 7474 2×D PET | A4 | 36-10507400 / | 74LS74 2×D PET |
| 36-0747401 | FF w/P&C PDIP | | 36-0747402 | FF w/P&C PDIP |

Notes

This component substitution reduces the overall power consumption.

IMSAI ECO 24-0002

Document Revision History

| Revision | Date | Initial | Description |
|----------|------------|---------|-------------|
| 0 | 2024-08-29 | REW | Original. |

IMSAI ECO 24-0002 2