

IMSAI ECO 24-0003

Engineering Change Order for: PIO 4 Rev-2

Summary

Component substitutions due to obsolescence.

Details

The following components may have been discontinued and may be substituted according to the following table:

Parastream / IMSAI Part #	Component	Designators	Parastream / IMSAI Part #	Substitution
36-1000200 / 36-0740201	7402 4×2-In NOR PDIP	C11	36-10500200 / 36-0740202	74LS02 4×2-In NOR PDIP
36-1000400 / 36-0740401	7404 6× Inverter PDIP	B8, B10	36-10500400 / 36-0740402	74LS04 6× Inverter PDIP
36-10002700 / 36-0742701	7427 3×3-In NOR PDIP	B11	36-10502700 / 36-0742702	74LS27 3×3-In NOR PDIP

Notes

These substitutions are not mandatory if all the components in the table are available. All or none of the component substitutions must be made. No individual substitutions are allowed.

These component substitutions reduce the overall power consumption.

Document Revision History

Revision	Date	Initial	Description
0	2024-08-29	REW	Original.