

IMSAI ECO 24-0007

Engineering Change Order for: MIO Rev-2

Summary

Component substitutions due to obsolescence.

Details

The following components may have been discontinued and may be substituted according to the following table:

Parastream / IMSAI Part #	Component	Designators	Parastream / IMSAI Part #	Substitution
36-10036700 / 36-7436701	74367 6×Buffer w/3S Out PDIP	U6, U41 through U43	36-10536700 / 36-7436702	74LS367 6× Buffer w/3S Out PDIP

Notes

This component substitution reduces the overall power consumption.

Document Revision History

Revision	Date	Initial	Description
0	2024-08-29	REW	Original.